


# Rotary Hoe Pro Wheel Sensor System



1. Passive components (resistors, capacitors) not shown.
2. Signal line is HIGH (5V) when wheel is moving.  
Second two hookups of 74LS02 could provide complimentary output.

